

APARTMENTS / FIRE DOOR REPLACEMENT WORKS

The Bails

FireBlocked365 carried out apartment entrance and services cupboard door replacements at The Bails. Four before-and-after comparisons show the installation stages and fitted timber-finish doors.



01 / BEFORE & AFTER

Entrance: internal view

The prepared doorway is shown beside a fitted timber-finish entrance door with an overhead closer, door viewer, lever handle, lock and security chain.



02 / BEFORE & AFTER

Entrance replacement

Exposed framing is visible during preparation. The fitted door is shown with a timber finish, overhead closer, viewer, lever handle and security chain.

A coordinated timber finish for entrances and service areas.

Entrance & services cupboard

Further project views showing the apartment entrance finish and the enclosed services cupboard.



03 / BEFORE & AFTER

Apartment entrance

The corridor-side comparison shows an open entrance followed by a fitted timber-finish door within a white surround, with a door viewer, lever handle and lock.



04 / BEFORE & AFTER

Services cupboard

The open cupboard reveals the service pipework during installation. The fitted timber-finish door includes locking hardware and fire door keep-locked signage.

Planning fire door works at your premises?

Contact FireBlocked365 to discuss surveys, maintenance and replacement doors.
info@fireblocked365.com | 0161 669 2577 | www.fireblocked365.com